

ZAMAK INGOT ANALYSIS

	Zamak 2	Zamak 2	Zamak 3	Zamak 3	Zamak 3	Zamak 4	Zamak 5	Zamak 6
Al	4%	4%	4%	4%	4%	4%	4%	4%
Cu	3%	3%	---	---	---	3%	1%	1.25%
Mg	0.1%	0.03%	0.1%	0.04%	---	---	0.03%	---
Zn	Zinc Purity 99.97% - 99.99%							